Play Area / Equipment Operational Inspection

conducted for

Llanharry Recreation Ground

Document No.

000078

Audit Title

LLANHARRY COMMUNITY COUNCIL

Conducted on

30/04/2019, 12:15

Prepared by

Jerry Widdas

Personnel

Jerry Widdas

Score

7/8 - 87.5%

Completed on

16/05/2019, 09:38

Audit - 7/8 - 87.5%

	Question	Response	Details	
GENERAL SIT	E DESCRIPTION	Score (1/1) 100%		
Detail:		Yes	The recreation ground consists of a play area fenced by steel bow top fencing with self closing gates A MUGA kick about area and a youth shelter Both areas are accessed by Tarmac pathways Benches and picnic tables are located within the play area and also outside the play area boundary	
Appendix 1	Appendix 2 App	pendix 3 App	pendix 4 Appendix 5	
ITEM			Score (6/6) 100%	

	Question		Respor	nse		Details	
Manufacturer ide installation	ntification and date	of	Yes		1 X 2 sea Urban Re 1 X Tradir Leisure 1 X Tradir Leisure 1 X Whee installed 1 X Multi 1 X Steel 1 X Frees 2 X Sprin 1 X Teen 1 X Canti Recreatio 9 X Fitne Recreatio 1 X Spinr	rea supplied by PP at swing supplied a ecreation in 2016 tional cradle seat s tional Igloo climbe elchair roundabout Urban Recreation player Unit Record cable ride Record standing slide Record stand	and installed by swing Wicksteed r Wicksteed supplied and Dec 2018 d Play l Play ord Play rld Systems lvie Engineering ied Urban urban and installed
				0			
Appendix 6	Appendix 7	Append	lix 8	App	endix 9	Appendix 10	Appendix 11
Appendix 12	Appendix 13	Appendix 14		Appendix 15		Appendix 16	Appendix 17
		• • • • • • • • • • • • • • • • • • •					
Appendix 18	Appendix 19	Appendi	ix 20	Арре	endix 21	Appendix 22	
Item Condition			Safe			ne of inspection all d to be in a safe a n.	

Questic	on .	Resp	onse	Details	
·	711	ПСОР	01130	Details	
Safety Surfacing				All items of play equipment are located on wet pour rubber safety surfacing Moss starting to collect on safety surface, monitor	
		Safe		The surfacing is shrinking back from the perimeter edging, currently there an no trip points but monitor for any further deterioration	
Appendix 23 Appe	ndix 24 Appendi	x 25			
Equipment Findings		Sa	fe	A small fire has caused minor damage to the ball court surface, an additional fire in the opposite corner has caused minor damage to the ball court surface and paintwork on the steel grid	
Appendix 26 Appe	ndix 27 Appendi	x 28			
Safety Surfacing Findings	3	Safe			
Recommendations	Yes				
Other comments				Score (0/1) 0%	
			0		
Inspector Sign Off					
	Jerry Widdas Rou And Operational Inspector (Cert OF		16/05/ 09:37	1 /	

Media





Appendix 1

Appendix 2





Appendix 3

Appendix 4





Appendix 5 Appendix 6





Appendix 7 Appendix 8





Appendix 9 Appendix 10





Appendix 11 Appendix 12





Appendix 13 Appendix 14





Appendix 15 Appendix 16





Appendix 17

Appendix 18





Appendix 19

Appendix 20





Appendix 21 Appendix 22






Appendix 23 Appendix 24





Appendix 25



Appendix 26



Appendix 27

Appendix 28