

# Play Area / Equipment Operational Inspection

conducted for

# Llanharry Recreation Ground

**Document No.**

000078

**Audit Title**

LLANHARRY COMMUNITY COUNCIL

**Conducted on**

04/11/2019, 12:28

**Prepared by**

Jerry Widdas

**Personnel**

Jerry Widdas

**Score**


















7/8 - 87.5%








**Completed on**


04/11/2019, 12:30

## Audit - 7/8 - 87.5%

Question	Response	Details
<b>GENERAL SITE DESCRIPTION</b>		Score (1/1) 100%
Detail:	Yes	<p>The recreation ground consists of a play area fenced by steel bow top fencing with self closing gates</p> <p>A MUGA kick about area and a youth shelter</p> <p>Both areas are accessed by Tarmac pathways</p> <p>Benches and picnic tables are located within the play area and also outside the play area boundary</p>
<div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;">  Appendix 1         </div> <div style="text-align: center;">  Appendix 2         </div> <div style="text-align: center;">  Appendix 3         </div> <div style="text-align: center;">  Appendix 4         </div> <div style="text-align: center;">  Appendix 5         </div> <div style="text-align: center;">  Appendix 6         </div> </div> <div style="margin-top: 20px; text-align: center;">  Appendix 7         </div>		
<b>ITEM</b>		Score (6/6) 100%

Question	Response	Details
Manufacturer identification and date of installation	Yes	MUGA area supplied by PPL date unknown 1 X 2 seat swing supplied and installed by Urban Recreation in 2016 1 X Traditional cradle seat swing Wicksteed Leisure 1 X Traditional Igloo climber Wicksteed Leisure 1 X Wheelchair roundabout supplied and installed Urban Recreation Dec 2018 1 X Multiplayer Unit Record Play 1 X Steel cable ride Record Play 1 X Freestanding slide Record Play 2 X Spring animals Playworld Systems 1 X Teen Shelter David Ogilvie Engineering 1 X Cantilever Swing supplied Urban Recreation 2016 9 X Fitness Items supplied Urban Recreation October 2017 1 X Spinning Cup supplied and installed Urban Recreation Dec 2018
<div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center;"> Appendix 8</div> <div style="text-align: center;"> Appendix 9</div> <div style="text-align: center;"> Appendix 10</div> <div style="text-align: center;"> Appendix 11</div> <div style="text-align: center;"> Appendix 12</div> <div style="text-align: center;"> Appendix 13</div> <div style="text-align: center;"> Appendix 14</div> <div style="text-align: center;"> Appendix 15</div> <div style="text-align: center;"> Appendix 16</div> <div style="text-align: center;"> Appendix 17</div> <div style="text-align: center;"> Appendix 18</div> <div style="text-align: center;"> Appendix 19</div> <div style="text-align: center;"> Appendix 20</div> <div style="text-align: center;"> Appendix 21</div> <div style="text-align: center;"> Appendix 22</div> <div style="text-align: center;"> Appendix 23</div> <div style="text-align: center;"> Appendix 24</div> </div>		
Item Condition	Safe	At the time of inspection all the equipment was found to be in a safe and useable condition.

Question	Response	Details
Safety Surfacing	Safe	<p>All items of play equipment are located on wet pour rubber safety surfacing</p> <p>Moss starting to collect on safety surface, monitor</p> <p>The surfacing is shrinking back from the perimeter edging, currently there are no trip points but monitor for any further deterioration</p>
<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>Appendix 25</p> </div> <div style="text-align: center;">  <p>Appendix 26</p> </div> <div style="text-align: center;">  <p>Appendix 27</p> </div> </div>		
Equipment Findings	Safe	<p>A small fire has caused minor damage to the ball court surface, an additional fire in the opposite corner has caused minor damage to the ball court surface and paintwork on the steel grid</p> <p>The Spring stopper at the end of the cable ride has broken, this is not currently a safety issue but may deteriorate further with time, monitor and plan to replace at convenient time in the future</p>
<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>Appendix 28</p> </div> <div style="text-align: center;">  <p>Appendix 29</p> </div> <div style="text-align: center;">  <p>Appendix 30</p> </div> <div style="text-align: center;">  <p>Appendix 31</p> </div> </div>		
Safety Surfacing Findings	Safe	
Recommendations	Yes	Plan ahead to replace cable ride spring
<b>Other comments</b>		Score (0/1) 0%
		No
<b>Inspector Sign Off</b>		

Question		Response	Details
	Jerry Widdas Routine And Operational Inspector (Cert OP1200)	04/11/2019 12:29	

# Media



Appendix 1



Appendix 2



Appendix 3



Appendix 4



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11



Appendix 12





Appendix 13



Appendix 14



Appendix 15



Appendix 16



Appendix 17



Appendix 18



Appendix 19



Appendix 20



Appendix 21



Appendix 22



Appendix 23



Appendix 24



Appendix 25



Appendix 26



Appendix 27



Appendix 28



Appendix 29



Appendix 30



Appendix 31