Play Area / Equipment Operational Inspection

LLANHARRY COMMUNIT	Y COUNCIL	Complete
Score	100% Flagged items	0 Actions 0
Document No.		000078
Audit Title		LLANHARRY COMMUNITY COUNCIL
Client / Site		Llanharry Recreation Ground
Conducted on		05.05.2023 11:15 BST
Prepared by		Jerry Widdas
Location		Llanharry
Personnel		
Jerry Widdas		

GENERAL SITE DESCRIPTION

Detail:

The recreation ground consists of a play area fenced by steel bow top fencing with self closing gates

A MUGA kick about area and a youth shelter

Both areas are accessed by Tarmac pathways

Benches and picnic tables are located within the play area and also outside the play area boundary













Photo 1

Photo 2

Photo 3

Photo 4

Photo 5

Photo 6



Photo 7



MUGA area supplied by PPL date unknown

- 1 X 2 seat swing supplied and installed by Urban Recreation in 2016
- 1 X Traditional cradle seat swing Wicksteed Leisure
- 1 X Traditional Igloo climber Wicksteed Leisure
- 1 X Wheelchair roundabout supplied and installed Urban Recreation Dec 2018
- 1 X Multiplayer Unit Proludic installed Feb 2022
- 1 X Steel cable ride Record Play
- 1 X Freestanding slide Record Play
- 2 X Spring animals Fahr Industries installed Feb 2022
- 1 X Teen Shelter David Ogilvie Engineering
- 1 X Cantilever Swing supplied Urban Recreation 2016
- 9 X Fitness Items supplied Urban Recreation October 2017
- 1 X Spinning Cup supplied and installed Urban Recreation Dec 2018





Photo 9







Photo 12

Photo 8

Photo 10

Photo 11

Photo 13

100%

100%



Photo 20



Photo 22

All items of play equipment are located on wet pour rubber safety surfacing



Item Condition

At the time of inspection all the equipment was found to be in a safe and useable condition





Safety Surfacing



Photo 26



Equipment Findings

One of the basket swing suspension ropes has been wrapped, monitor

A small fire has caused minor damage to the ball court surface, an additional fire in the opposite corner has caused minor damage to the ball court surface and paintwork on the steel grid

There is some wear on the toddler swing chains, monitor and plan for replacement in the future

There is a rubber cover missing from one of the sit up benches

At the time of inspection the access gate was not self closing

The stopper spring on the cable ride has once again started to break, would suggest using a heavier duty spring next time it is changed.



Photo 28

Photo 29

Photo 30

Photo 31

Photo 32



Photo 33

Safety Surfacing Findings

At the time of inspection all surfaces were found to be in a safe and useable condition although there are some areas of joint separation which should be monitored

The basket swing area has some self seeded grass growth that could be treated if possible while it is still manageable







Photo 34

Photo 35

monitor items noted	Other comments	1009
	Other comments	100%

Inspector Sign Off

Jerry Widdas Routine And Operational Inspector (Cert OP1200) 05.05.2023 11:28 BST

Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4



Photo 6



Photo 7



Photo 9



Photo 11



Photo 13



Photo 8



Photo 10



Photo 12



Photo 14



Photo 15



Photo 17



Photo 19



Photo 21



Photo 16



Photo 18



Photo 20



Photo 22



Photo 23



Photo 24



Photo 26



Photo 28



Photo 25



Photo 27



Photo 29




Photo 31



Photo 33



Photo 30



Photo 32



Photo 34



Photo 35



Photo 36