# Play Area / Equipment Operational Inspection

LLANHARRY COMMUNITY COUNCIL Comple					
Score	8 / 8 (100%)	Flagged items	0	Actions	0
Document No.					000078
Audit Title				LLANHARF	RY COMMUNITY COUNCIL
Client / Site				Llanharry Rec	reation Ground
Conducted on				31.08.	2023 09:20 BST
Prepared by					Jerry Widdas
Location					Llanharry
Personnel					
Jerry Widdas					

## Audit

## **GENERAL SITE DESCRIPTION**

#### Detail:

The recreation ground consists of a play area fenced by steel bow top fencing with self closing gates

A MUGA kick about area and a youth shelter

Both areas are accessed by Tarmac pathways

Benches and picnic tables are located within the play area and also outside the play area boundary













Photo 1

Photo 2

Photo 3

Photo 4

Photo 5

Photo 6



Photo 7

# ITEM

6/6(100%)


### Manufacturer identification and date of installation

MUGA area supplied by PPL date unknown

- 1 X 2 seat swing supplied and installed by Urban Recreation in 2016
- 1 X Traditional cradle seat swing Wicksteed Leisure
- 1 X Traditional Igloo climber Wicksteed Leisure
- 1 X Wheelchair roundabout supplied and installed Urban Recreation Dec 2018
- 1 X Multiplayer Unit Proludic installed Feb 2022
- 1 X Steel cable ride Record Play
- 1 X Freestanding slide Record Play
- 2 X Spring animals Fahr Industries installed Feb 2022
- 1 X Teen Shelter David Ogilvie Engineering
- 1 X Cantilever Swing supplied Urban Recreation 2016
- 9 X Fitness Items supplied Urban Recreation October 2017
- 1 X Spinning Cup supplied and installed Urban Recreation Dec 2018



1/1(100%)



#### Item Condition

At the time of inspection all the equipment was found to be in a safe and useable condition





Photo 24

## Safety Surfacing

All items of play equipment are located on wet pour rubber safety surfacing



Photo 26



**Equipment Findings** 





Safe

Saf

One of the basket swing suspension ropes has been wrapped, monitor

A small fire has caused minor damage to the ball court surface, an additional fire in the opposite corner has caused minor damage to the ball court surface and paintwork on the steel grid

There is some wear on the toddler swing chains, monitor and plan for replacement in the future

There is a rubber cover missing from one of the sit up benches

Access gate is now closing!

The stopper spring on the cable ride has once again started to break, would suggest using a heavier duty spring next time it is changed.

The pendulum seat on the cable ride has damage to the chain cover that should be planned for change.













Photo 28

Photo 29

Photo 30

Photo 31

Photo 32

Photo 33

#### Safety Surfacing Findings

At the time of inspection all surfaces were found to be in a safe and useable condition although there are some areas of joint separation which should be monitored

The basket swing area has some self seeded grass growth that could be treated if possible while it is still manageable

One corner of the roundabout surfacing has been subsiding over the years and continues to drop









Recommendations monitor items noted Photo 36

Other comments				
	Yes			
Schedule inspection for October 2nd				
Inspector Sign Off				

Jerry Widdas Routine And Operational Inspector (Cert OP1200) 31.08.2023 09:37 BST

# Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4



Photo 6



Photo 7



Photo 9



Photo 11



Photo 13



Photo 8



Photo 10



Photo 12



Photo 14



Photo 15



Photo 17



Photo 19



Photo 21



Photo 16



Photo 18







Photo 22



Photo 23



Photo 24



Photo 26



Photo 28





Photo 27








Photo 31



Photo 33



Photo 30





Photo 34





Photo 36



Photo 37