MANAGEMENT RISK ASSESSMENT POLICY 2022-2023

Assessment Criteria

Rating Potential Consequence Score 1-5 Classification

Likelihood of happening Score 1-5 6-10 Medium

1-5

Low

Severity Level Score—Potential Consequence X Likelihood 11-15 High

16-25 Very High

Assessment carried out on 27th March 2023

Area Buildings Etc.	Location	Potential Consequence	Likelihood	Severity Score	y Class	Measure to be taken to Reduce/Minimise/Control Risk
COMMUNITY ASSETS						
Playing Field	North side boundary entrance to Fox & Hounds public house	1	2	2	Medium Low	Letter has been sent (annually) to Landlord informing him that there is no public right of way and that he is responsible for any claims arising from the construction of a pathway in the playing field. Uneven ground/surfaces/trees/hedges — no action to be taken.
Playing Field	South side boundary behind Spar including main entrance to playing field.	1 1	2 5	2 5	Low	Uneven ground/surfaces/trees/hedges – no action to be taken Exposed tree roots – no action to be taken.
Playing Field	East side boundary in front of Community Centre	1	5	5	Low	Uneven ground/surfaces – no action to be taken. RCTCBC Litter bin with unlockable door and no liner.
Playing Field	West side boundary to rear of properties along Llanharry Road	1 1	5	5	Low	Uneven ground/surfaces

1

MANAGEMENT RISK ASSESSMENT POLICY 2022-2023

Assessment Criteria

Rating Potential Consequence Score 1-5 Classification 1-5 Low

Likelihood of happening Score 1-5 6-10 Medium

Very High

16-25

Severity Level Score—Potential Consequence X Likelihood 11-15 High

Area Buildings Etc.	Location	Potential Consequence	Likelihood	Severity Score	y Class	Measure to be taken to Reduce/Minimise/Control Risk
			1 1			
MUGA	Playing Field	1	5	5	Low	Non – identified. See monthly Inspection reports.
	Play Area	N/a	N/a	N/a	N/a	Monthly independent inspections.
		1	5	5	Low	Grass growing through play surfacing under cantilever swing
		1	5	5	Low	Paint scrapped off cantilever swing arm.
<u>BURIAL</u> GROUNDS						
Burial Ground	Cowbridge Road	2	3	6	Medium	Uneven ground/surfacing/trees/hedges – no action to be taken.
		2	3	6	Medium	Moss on paths.
Burial Ground Unused	Church burial ground	2	3	6	Medium	Uneven ground/surfacing/trees/hedges – no action to be taken. Moss on paths.
		5	5	25	V High	Slates embedded in ground having slipped from roof! Informed Church Warden 27/03/23.
<u>ALLOTMENTS</u>	Fforest Road	2	2	4	Low	Uneven ground/surfacing/trees/hedges – no action to be taken.

MANAGEMENT RISK ASSESSMENT POLICY 2022-2023

Assessment Criteria

Rating Potential Consequence Score 1-5 **Classification** 1-5

Likelihood of happening Score 1-5 6-10 Medium

Low

Severity Level Score—Potential Consequence X Likelihood 11-15 High 16-25 Very High

Area	Location	Potential	Likelihood	Severity	Class	Measure to be taken to
Buildings		Consequence		Score		Reduce/Minimise/Control Risk
Etc.						
	Laureldene	2	2	4	Low	Uneven ground/surfacing/trees/hedges – no action to be taken.
		5	3	15	High	Uncovered water trough & water barrels– Inform Allotment Assoc.
	Strip of land running from East to West alongside M 4.	1	5	5	Low	Uneven ground/surfacing/trees/hedges – no action to be taken.
Ambulance Hall, Grounds	Birchgrove	2	2	4	Low	Uneven ground/surfacing- no action to be taken.
<u>BUILDINGS</u>						
Ambulance Hall	Birchgrove	1	2	2	Low	Loss of keys to Hall – register of keyholders set up.
		1	2	2	Low	Loss of fob to Garage.
Garage		2	2	4	Low	Uneven ground/surfacing – no action to be taken.
Cemetery Shed	Cowbridge Road	1	2	2	Low	Loss of keys to shed. Register of authorised key holders and users set up. Uneven ground/surfacing/trees/hedges – no action to
		2	3	6	Medium	be taken.
War Memorial	Ty Isaf	5	1	5	Low	Non-identified

MANAGEMENT RISK ASSESSMENT POLICY 2022-2023

Assessment Criteria

Rating Potential Consequence Score 1-5 **Classification** 1-5 Low

Likelihood of happening Score 1-5 6-10 Medium

Severity Level Score—Potential Consequence X Likelihood 11-15 High 16-25 Very High

Area Buildings Etc.	Location	Potential Consequence	Likelihood	Severity Score	Class	Measure to be taken to Reduce/Minimise/Control Risk
BUS SHELTERS	Tylacoch Avenue	1	5	5	Low	Uneven ground/surfacing/hedges – no action to be taken.
	Red Hill	1	5	5	Low	Uneven ground/surfacing – no action to be taken.
	Post Office	1	5	5	Low	Non- identified.
	Birchgrove	1	5	5	Low	Uneven ground/surfacing – no action to be taken.
	Ty Isaf	1	5	5	Low	Non- identified.
	Tylagarw	1	5	5	Low	Non-identified.
PUBLIC SEATS	Public seats at various locations	1	5	5	Low	Uneven ground/surfacing – no action to be taken.
COUNCIL OFFICE	Groes Sannor, Degar Road	1	5	5	Low	Uneven ground/surfacing – no action to be taken. Lone working – see Lone Working Policy.
FINANCE & MANAGEMENT	Risk of Council not being able to continue its business due to an unexpected or tragic circumstance.	5	1	5	Low	All files and recent records are kept at the Clerk's home. Regular back-ups are made to an external hard drive.
	Insurance	5	1	5	Low	Review provision annually.
	Data Protection	5	1	5	Low	Ensure annual renewal of registration and continual review of compliance.

MANAGEMENT RISK ASSESSMENT POLICY 2022-2023

Assessment Criteria

Rating	Potential Consequence Score 1-5	Classification	1-5	Low

Likelihood of happening Score 1-5 6-10 Medium

Severity Level Score—Potential Consequence X Likelihood 11-15 High 16-25 Very High

Area	Location	Potential	Likelihood	Severity	Class	Measure to be taken to
Buildings		Consequence		Score		Reduce/Minimise/Control Risk
Etc.						

Councillor J Dilworth	Councillor V Davies	Clerk
Date		